

VCDS  
Windows Based VAG/VAS Emulator  
VCDS Version: Release 11.11.3 Data version: 20120401  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000

Self-Diagnosis Log  
Sunday,06, August,2017,18:11:46:32264

VIN: TMBUH61Z382073714 License Plate:  
Mileage: 175800km-109237mi Repair Order:

Chassis Type: 1K0  
Scan: 01 03 08 09 15 16 17 19 25 42 44 46 52 55 56 62 72

VIN: TMBUH61Z382073714 Mileage: 175800km/109237miles

01-Engine -- Status: Malfunction 0010  
03-ABS Brakes -- Status: OK 0000  
04-Steering Angle -- Status: OK 0000  
08-Auto HVAC -- Status: Malfunction 0010  
09-Cent. Elect. -- Status: OK 0000  
15-Airbags -- Status: OK 0000  
16-Steering wheel -- Status: OK 0000  
17-Instruments -- Status: OK 0000  
19-CAN Gateway -- Status: OK 0000  
25-Immobilizer -- Status: OK 0000  
42-Door Elect, Driver -- Status: OK 0000  
44-Steering Assist -- Status: OK 0000  
46-Central Conv. -- Status: OK 0000  
52-Door Elect, Pass. -- Status: OK 0000  
55-Xenon Range -- Status: OK 0000  
56-Radio -- Status: Malfunction 0010  
62-Door, Rear Left -- Status: OK 0000  
72-Door, Rear Right -- Status: OK 0000

---

VCDS  
Self-Diagnosis Log  
Sunday, 06, August, 2017, 18:11:46:32264  
Page 2

VIN: TMBUH61Z382073714 License Plate:

Address 01: Engine Labels: 03G-906-018-BMN.clb  
Part No SW: 03G 906 018 EL HW: 03G 906 018 EL  
Component: R4 2.01 PPD1.2 9953  
Revision: --H42--- Serial number: SKZ7Z0G4517116  
Coding: 0000072  
Shop #: WSC 00191 264 15243  
VCID: 73EFC11512AE091

1 Fault Found:

008194 - Particulate Trap Bank 1  
P2002 - 006 - Efficiency Below Threshold - Intermittent

Freeze Frame:

Fault Status: 00000001  
Fault Priority: 1  
Fault Frequency: 18  
Reset counter: 40  
Mileage: 175705 km  
Time Indication: 0  
Date: 2000.00.00  
Time: 12:20:09

Freeze Frame:

RPM: 2496 /min  
Torque: 96.0 Nm  
Speed: 123.0 km/h  
Pressure: 0.0 mbar  
Text: 0 mbar  
Text: 352 C  
Temperature: 15.0°C

Readiness: N/A

-----  
Address 03: ABS Brakes Labels: 1K0-907-379-MK60-F.lbl  
Part No SW: 1K0 907 379 AC HW: 1K0 907 379 AC  
Component: ESP FRONT MK60 0101  
Revision: 00H11001  
Coding: 0006786  
Shop #: WSC 73430 790 00000  
VCID: 73EFC11512AE091

No fault code found.  
-----

VIN: TMBUH61Z382073714 License Plate:

Address 08: Auto HVAC Labels: 1K0-907-044.lbl  
Part No SW: 1Z0 907 044 R HW: 1Z0 907 044 R  
Component: ClimatronicPQ35 110 0402  
Revision: 00110021 Serial number: 000000000000000  
Shop #: WSC 00000 000 00000  
VCID: 458B4FCD0CBAC71

1 Fault Found:  
00229 - Refrigerant Pressure  
002 - Lower Limit Exceeded

-----  
Address 09: Cent. Elect. Labels: 3C0-937-049-30-H.lbl  
Part No SW: 3C0 937 049 AJ HW: 3C0 937 049 AJ  
Component: Bordnetz-SG H54 2202  
Revision: 00H54000 Serial number: 00000005041312  
Coding: 018A0F131004140000110D000000000000087F065C00000000000000000000000  
Shop #: WSC 73430 790 00000  
VCID: 71E3CB1D68B23B1

Subsystem 1 - Part No: 1Z2 955 119 C Labels: 1KX-955-119.CLB  
Component: Wischer 031007 022 0601  
Coding: 0005223  
Shop #: WSC 73430

No fault code found.

-----  
Address 15: Airbags Labels: 1K0-909-605.lbl  
Part No SW: 1K0 909 605 AA HW: 1K0 909 605 AA  
Component: Q4 AIRBAG VW8 027 0900  
Revision: 11027000 Serial number: 003B5D136TE%  
Coding: 0020788  
Shop #: WSC 73430 790 00000  
VCID: 6BDFD9754A9ED11

No fault code found.

-----  
Address 16: Steering wheel Labels: 1K0-953-549-MY8.lbl  
Part No SW: 1K0 953 549 BC HW: 1K0 953 549 BC  
Component: Lenksäulenmodul 036 0070  
Coding: 0000012  
Shop #: WSC 73430 790 00000  
VCID: 74EDC20917A00E9

No fault code found.

VIN: TMBUH61Z382073714 License Plate:

Address 17: Instruments Labels: 1K0-920-xxx-17.lbl  
Part No SW: 1Z0 920 912 E HW: 1Z0 920 912 E  
Component: KOMBIINSTRUMENT VD1 1610  
Revision: V1610056 Serial number: SKZ7Z0G4517116  
Coding: 0007401  
Shop #: WSC 20002 576 93634  
VCID: 377735054656A51

No fault code found.

-----  
Address 19: CAN Gateway Labels: 1K0-907-530.lbl  
Part No SW: 1K0 907 530 L HW: 1K0 907 951  
Component: J533 Gateway H07 0052  
Revision: H07 01 Serial number: 111007F1001876  
Coding: E9817F060002022303  
Shop #: WSC 73430 790 00000  
VCID: 30650E19A338729

No fault code found.

-----  
Address 25: Immobilizer Labels: 1K0-920-xxx-25.clb  
Part No SW: 1Z0 920 912 E HW: 1Z0 920 912 E  
Component: IMMO VD1 1610  
Revision: V1610056 Serial number: SKZ7Z0G4517116  
Shop #: WSC 00000 000 00000  
VCID: 377735054656A51

No fault code found.

-----  
Address 42: Door Elect, Driver Labels: 1K0-959-701-MIN3.lbl  
Part No SW: 1T0 959 701 D HW: 1T0 959 701 D  
Component: Tuer-SG 006 1204  
Coding: 0000756  
Shop #: WSC 73430 790 00000  
VCID: 387536394B48AA9

No fault code found.

-----  
Address 44: Steering Assist Labels: 1Kx-909-14x-44.clb  
Part No: 1K2 909 144 M  
Component: EPS\_ZFLS Kl.074 H08 1901  
Shop #: WSC 73430 000 90108  
VCID: 36693801415C5C9

No fault code found.

-----

VIN: TMBUH61Z382073714 License Plate:

Address 46: Central Conv. Labels: 1K0-959-433-MAX.clb  
Part No SW: 1K0 959 433 BT HW: 1K0 959 433 BT  
Component: KSG PQ35 G2 020 0204  
Revision: 00020000 Serial number: 000000000000000  
Coding: 90801A085283007F3F04850540085F96907CA0  
Shop #: WSC 20002 576 93634  
VCID: 830F11D5C20EB91

Subsystem 5 - Part No: 1Z0 951 171  
Component: Innenraumueberw.008 4801  
Coding: 00000000  
Shop #: WSC 20002

Part No: 1K0 951 605 D  
Component: LIN BACKUP HORN H07 9001

Component: NGS n.mounted

No fault code found.

-----  
Address 52: Door Elect, Pass. Labels: 1K0-959-702-MIN3.lbl  
Part No SW: 1T0 959 702 D HW: 1T0 959 702 D  
Component: Tuer-SG 006 1204  
Coding: 0000756  
Shop #: WSC 73430 790 00000  
VCID: 3973333D7042B31

No fault code found.

-----  
Address 55: Xenon Range Labels: 1T0-907-357.lbl  
Part No: 1T0 907 357  
Component: Dynamische LWR 0003  
Coding: 0000007  
Shop #: WSC 73430 790 08192  
VCID: F4ED420997A08E9

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Sunday,06, August, 2017, 18:11:46:32264  
Page 6

VIN: TMBUH61Z382073714 License Plate:

Address 56: Radio Labels: 1K0-035-1xx-56.lbl  
Part No SW: 1Z0 035 161 C HW: 1Z0 035 161 C  
Component: Radio FO3 019 0040  
Revision: 00019000 Serial number: SKZ7Z3G0096141  
Coding: 0000402  
Shop #: WSC 73430 790 00000  
VCID: 2E591061B90C649

1 Fault Found:  
00856 - Radio Antenna  
011 - Open Circuit

-----  
Address 62: Door, Rear Left Labels: 1K0-959-703-GEN3.lbl  
Part No SW: 1K0 959 703 J HW: 1K0 959 703 J  
Component: Tuer-SG 006 1201  
Coding: 0000144  
Shop #: WSC 73430 790 1012544  
VCID: 377735054656A51

No fault code found.

-----  
Address 72: Door, Rear Right Labels: 1K0-959-704-GEN3.lbl  
Part No SW: 1K0 959 704 J HW: 1K0 959 704 J  
Component: Tuer-SG 006 1201  
Coding: 0000144  
Shop #: WSC 73430 790 1012544  
VCID: 387536394B48AA9

No fault code found.

End -----